












Region 1






ture

Fatigue crack




Fast fracture zone
Region 1



Fatigue crack
Region 2



Fast fracture zone
Region 3



Fatigue crack
Region 4

Fast fracture